
DE Montageanleitung

EN Assembly instruction
NL Montage instructie
ES Instrucciones de montaje
FR Instructions de montage
DA Monteringsvejledningen
SV Monteringsanvisningarna



HYMER



2230 / 2231

No.: 21000005

05/2024

Hymer-Leichtmetallbau GmbH & Co. KG

Käferhofen 10 | 88239 Wangen | GERMANY

Tel. +49 (0)75 22 700-702

technical-sales@hymer-alu.de | www.hymer-steigtechnik.de



M8	18 Nm
M10	49 Nm
M12	79 Nm



4x








M12x40

4x





M12


















Σ 	L	
≥ 12	$\leq 1000 \text{ mm}$	1x
≥ 6	$> 1000 \text{ mm}$	1x












$\angle$	A	B	C
75°	147	= D	= E
70°	152	= D	= E
65°	162	= D	= E
60°	167	= D	= E
55°	182	= D	= E
50°	197	= D	= E
45°	212	= D	= E
40°	227	= D	= E
35°	247	= D	= E




























M8x25 M8

